

April, 18<sup>th</sup> 2024

Page 1

# MXS 1.2 Release history

Version	Date	Change/additions
02.42.01	Apr, 18th 2024	<ul> <li>ACC2 and ACC2 Open support</li> <li>External modules</li> <li>02.40.73 ACC</li> <li>02.40.95 ACC2</li> <li>02.40.95 GPS09c/GPS09c Open/GPS09c Pro Open</li> <li>02.40.85 GPS09</li> <li>02.40.72 GPS09B</li> <li>1.32.30 GS-Dash</li> </ul>
02.40.77	Oct, 11th 2023	<ul> <li>Improved AiM CAN NET</li> <li>External modules</li> <li>25.49 LCU-One CAN (improved warm up handling)</li> <li>01.32.28 MMOD Strada Logger (fix Net table in download data)</li> <li>02.40.73 ACC (fix sample time bug caused no recorded data)</li> </ul>
02.40.53	Feb, 7th 2023	<ul> <li>GPS09C support</li> <li>External modules</li> <li>No changes</li> </ul>
02.40.40	Nov, 23rd 2022	<ul> <li>Added predictive reference lap management</li> <li>External modules</li> <li>No changes</li> </ul>
02.40.21	Jul, 27th 2022	<ul> <li>New expansion boards (GSDASH2, RIO2_B, Shiftlight_B) support</li> <li>External modules</li> <li>02.40.02 RIO2 Module B</li> <li>02.40.10 Shiftlight Module B</li> <li>02.40.21 GSDASH2</li> <li>01.32.16 GSDASH</li> </ul>



April, 18<sup>th</sup> 2024

Page 2

# MXS 1.2 Release history

Version	Date	Change/additions
02.40.00	May, 17th 2022	SmartyCam 3 Sport support External modules No changes
02.38.05	Feb, 17th 2022	<ul> <li>Added GPS09B device support</li> <li>External modules</li> <li>02.38.03 GPS09B</li> </ul>
02.36.76	Sep, 10th 2021	<ul> <li>Fixed digital speed parameters from RS3 configuration setup</li> <li>External modules</li> <li>02.36.64 GPS09: Improved GPS data synchronization</li> </ul>
02.34.29	Nov, 25th 2020	<ul> <li>Added GPS09 support</li> <li>External modules</li> <li>35.65 GPS Module: Fix Masterclock received from master that caused bad values in GPS data timestamp</li> </ul>
02.32.81	Jul, 17th 2020	<ul> <li>Fixed RPM issue due to wrong RPM factor handling</li> <li>External modules</li> <li>No changes</li> </ul>
02.32.72	May, 22nd 2020	<ul> <li>Simulators handling</li> <li>Added Hour/Date info from GPS tracks</li> <li>Added reference speed used to calculate odometers</li> <li>External modules</li> <li>No changes</li> </ul>
02.32.55	Apr, 23rd 2020	<ul> <li>General speed up in transmitting configuration</li> <li>Solved missing timeout on ECU channels for some serial protocol (RS232 and K-line) (AB#59)</li> <li>Improved track visualization</li> <li>Digital channels: bug fix on RPM input capture</li> <li>Fixed alarms based on BestDiff time</li> </ul> External modules No changes



April, 18<sup>th</sup> 2024

# MXS 1.2 Release history

Page 3

Version	Date	Change/additions
02.32.12	Feb, 10th 2020	Fixed bug that didn't enable the display page after rear camera visualization
		External modules
		No changes
02.32.09	Oct, 17th 2019	First Release including the new graphic engine which has the following improvements:
		Faster boot time
		Boot time independent from the number of configured pages
		Improvement in font visualization quality
		<ul> <li>Resizable fonts</li> <li>Colorable icons</li> </ul>
		This firmware release is compatible ***ONLY*** with the Race Studio 3 releases starting from the 03.30.00
		External modules
		<b>2.30.16</b> Shift Light Module: support for the new software release (v03.30.00)
		<b>35.64</b> GPS Module: improved GPS data synchronization
02.30.12	Jul, 11th 2019	Fixed display visualization when large font is used for GEAR measure
		Fixed bug on Trigger Commands when the action is configured as "Reset Alarms Command"
		External modules
		<b>40.63</b> Channel Expansion/TC Hub: no changes for these loggers
02.30.10	Jun, 12th 2019	Fixed bug locking the device in data recall
		AIM CAN network improvements
		Fixed the calibration of the Expansion channels
		External modules
		<b>40.62</b> Channel Expansion/TC Hub
		<b>35.61</b> GPS Module
02.30.06	May, 23rd 2019	Fixed reset gear calculation
		Popup management:
		Background color configurable from RS3
		Txt color configurable from RS3
		External modules
		No changes



April, 18<sup>th</sup> 2024

Page 4

# MXS 1.2 Release history

Version	Date	Change/additions
02.30.02	Apr, 19th 2019	Improved K-line protocols management
		Added open tracks management
		External modules
		No changes
02.26.57	Mar, 22nd 2019	Fix speed indication in miles for analog controls
		External modules
		No changes
02.26.55	Mar, 14th 2019	Improved ADC accuracy
		GPS page skipped when the vehicle is moving
		Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones)
		Fix bug on clear alarm by keypress
		Fix display bug which could lead to device resets with heavy configurations (multiple pages)
		External modules
		External modules
		No changes
		No changes
02.26.53	Feb, 14th 2019	
02.26.53	Feb, 14th 2019	No changes
02.26.53	Feb, 14th 2019	<ul> <li>Fixed inertial platform orientation</li> </ul>
02.26.53	Feb, 14th 2019	<ul> <li>No changes</li> <li>Fixed inertial platform orientation</li> <li>External modules</li> </ul>
02.26.53	Feb, 14th 2019	No changes
02.26.53		No changes = Fixed inertial platform orientation External modules = 02.26.51 Shift Light Module = Fixed issues with some ECUs No changes for the other modules
02.26.53 02.26.50	Feb, 14th 2019 Jan, 18th 2019	No changes
		No changes • Fixed inertial platform orientation External modules • 02.26.51 Shift Light Module



April, 18<sup>th</sup> 2024

# MXS 1.2 Release history

Page 5

Version	Date	Change/additions
Version	Date	change/additions
02.26.35	Dec, 5th 2018	Added management of Shift Light Module
		Added the support for auto brightness levels configuration (day brightness level, night brightness level and threshold are now fully configurable)
		External modules
		No changes
02.26.12	Oct, 30th 2018	Support for CAN Optical Lap (IRM_42)
		CAN network fixes
		I00Hz CAN output management
		External modules
		No changes
02.26.08	Oct, 15th 2018	Improved synchronization of GPS data
		External modules
		<b>35.60</b> GPS Module
		<b>25.47</b> Lambda
		<b>40.61</b> Channel Expansion/TC Hub
		<b>70.03</b> Remote buttons interface
02.26.06	Oct, 5th 2018	Fixed bug on Digital output priority handling
02.26.01	Oct, 1st 2018	Added support for rear cam and rear cam configuration menu
02.20.01	000, 1902010	Fix on units of measure visualization
02.24.04	Sep, 21st 2018	Support for RS232 protocols
02.22.96	Sep, 11th 2018	Fixed potentiometers calibration
		Improved display management when ECU CAN stream has very few fields
02.22.93	Sep, 4th 2018	Support for fuel set/reset using Race Studio 3
		Fix on visualized unit of measure
02.22.81	Jul, 27th 2018	Fixed Remote button interface compatibility
		Fixed multiplexed CAN protocols management