

## Solo 2 DL Release history

Version	Date	Change/additions
<b>02.42.01</b>	Apr, 18th 2024	<ul style="list-style-type: none"><li>▪ ACC2 and ACC2 Open support</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.40.73</b> ACC</li><li>▪ <b>02.40.95</b> ACC2</li><li>▪ <b>02.40.95</b> GPS09c/GPS09c Open/GPS09c Pro Open</li><li>▪ <b>02.40.85</b> GPS09</li><li>▪ <b>02.40.72</b> GPS09B</li><li>▪ <b>1.32.30</b> GS-Dash</li></ul>
<b>02.40.90</b>	Feb, 29th 2024	<ul style="list-style-type: none"><li>▪ Fix device lock in track creation procedure on device</li><li>▪ Fix Wi-Fi not power up in some cases (Wi-Fi OFF)</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.40.85</b>	Dec, 13th 2023	<ul style="list-style-type: none"><li>▪ Add external GPS support</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.40.85</b> GPS09</li></ul>
<b>02.40.80</b>	Nov, 28th 2023	<ul style="list-style-type: none"><li>▪ Improved CAN network</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.40.77</b>	Oct, 12th 2023	<ul style="list-style-type: none"><li>▪ Improved AiM CAN NET</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>25.49</b> LCU-One CAN (improved warm up handling)</li><li>▪ <b>01.32.28</b> MMOD Strada Logger (fix Net table in download data)</li><li>▪ <b>02.40.73</b> ACC (fix sample time bug caused no recorded data)</li></ul>

## Solo 2 DL Release history

Version	Date	Change/additions
<b>02.40.65</b>	Jul, 4th 2023	<ul style="list-style-type: none"><li>▪ Added ACC support</li></ul> <b>External modules</b> No changes
<b>02.40.53</b>	Feb, 16th 2023	<ul style="list-style-type: none"><li>▪ Fixed Italian language handling</li></ul> <b>External modules</b> No changes
<b>02.40.40</b>	Nov, 23rd 2022	<ul style="list-style-type: none"><li>▪ Added predictive reference lap management</li></ul> <b>External modules</b> No changes
<b>02.40.21</b>	Jul, 27th 2022	<ul style="list-style-type: none"><li>▪ Fixed IMU platform sensors orientation</li></ul> <b>External modules</b> No changes
<b>02.40.11</b>	Jun, 22nd 2022	<ul style="list-style-type: none"><li>▪ Improved GPS signal handling</li></ul> <b>External modules</b> No changes
<b>02.36.81</b>	Sep, 22nd 2021	<ul style="list-style-type: none"><li>▪ Fixed accelerometers, gyros and magnetometers channels not working in some devices</li></ul> <b>External modules</b> No changes
<b>02.36.76</b>	Sep, 10th 2021	<ul style="list-style-type: none"><li>▪ Production needs</li><li>▪ Added RPM max value in data recall best laps page</li><li>▪ Fixed accelerometers, gyros and magnetometers channels acquisition</li></ul> <b>External modules</b> No changes

## Solo 2 DL Release history

Version	Date	Change/additions
<b>02.36.34</b>	Jun, 11th 2021	<ul style="list-style-type: none"><li>▪ Improved GPS switch on procedure to prevent the "GPS ERROR" issue</li></ul> <b>External modules</b> No changes
<b>02.36.18</b>	Apr, 2nd 2021	<ul style="list-style-type: none"><li>▪ Improved GPS initialization</li><li>▪ Added 2 and 5 minutes to Auto-Off setup time in menu</li><li>▪ Fixed bug that could cause half RPM value</li></ul> <b>External modules</b> No changes
<b>02.34.29</b>	Nov, 25th 2020	<ul style="list-style-type: none"><li>▪ Production requirements</li></ul> <b>External modules</b> No changes
<b>02.32.86</b>	Aug, 21st 2020	<ul style="list-style-type: none"><li>▪ Signalling of expansions/Wi-Fi: the two upper left shiftlights blink blue</li><li>▪ Fix missing data recall graph</li></ul> <b>External modules</b> No changes
<b>02.32.78</b>	Jul, 10th 2020	<ul style="list-style-type: none"><li>▪ Fixed RPM issue due to wrong RPM factor handling</li></ul> <b>External modules</b> No changes
<b>02.32.74</b>	Jun, 15th 2020	<ul style="list-style-type: none"><li>▪ Fixed powerup bug that could cause the system to reset (indicated by red LED blinking slowly)</li></ul> <b>External modules</b> No changes
<b>02.32.72</b>	Jun, 9th 2020	<ul style="list-style-type: none"><li>▪ Japanese language update</li><li>▪ Improved timing of RS232/K-line communication (it helps with some ECU protocols)</li><li>▪ Added Hour/Date info from GPS tracks</li><li>▪ Added reference speed used to calculate odometers</li></ul> <b>External modules</b> No changes

## Solo 2 DL Release history

Page 4

Version	Date	Change/additions
<b>02.32.57</b>	Mar, 17th 2020	<ul style="list-style-type: none"><li>▪ Minor stability improvements</li></ul> <b>External modules</b> No changes
<b>02.32.52</b>	Mar, 9th 2020	NOTE: production-only release <ul style="list-style-type: none"><li>▪ Improved handling of poweroff after fast charge</li></ul> <b>External modules</b> No changes
<b>02.32.49</b>	Feb, 13th 2020	NOTE: production-only release <ul style="list-style-type: none"><li>▪ Improved battery handling</li><li>▪ Solved missing timeout on ECU channels for some serial protocol (RS232 and K-Line)</li></ul> <b>External modules</b> No changes
<b>02.30.10</b>	Jun, 12th 2019	<ul style="list-style-type: none"><li>▪ Fixed bug locking the device in data recall</li><li>▪ AIM CAN network improvements</li></ul> <b>External modules</b> No changes
<b>02.30.04</b>	May, 2nd 2019	<ul style="list-style-type: none"><li>▪ Fixed bug on track auto-learning enabling</li></ul> <b>External modules</b> No changes
<b>02.30.02</b>	Apr, 19th 2019	<ul style="list-style-type: none"><li>▪ Improved K-line protocols management</li><li>▪ Added open tracks management</li><li>▪ Added manual track creation on device</li><li>▪ In data recall added min speed in best lap page and in all laps page</li></ul> <b>External modules</b> No changes

## Solo 2 DL Release history

Page 5

Version	Date	Change/additions
<b>02.26.55</b>	Mar, 14th 2019	<ul style="list-style-type: none"><li>▪ Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones)</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.26.50</b>	Jan, 18th 2019	<ul style="list-style-type: none"><li>▪ Performance Race Mode: fix wrong units of measurement in data recall page (MPH and ft were shown but values were in km/h and m)</li><li>▪ ECU: support Adaptronics and Motec M4 ECU drivers</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.26.38</b>	Dec, 14th 2018	<ul style="list-style-type: none"><li>▪ Fixed calculated Performance Time</li><li>▪ Fixed "+/- Best Time" display visualization</li><li>▪ Added "laptime resume visualization" crossing the finish (it can be disabled by menu option)</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.26.12</b>	Oct, 30th 2018	<ul style="list-style-type: none"><li>▪ Support for Can Optical Lap(IRM_42)</li><li>▪ CAN network fixes</li><li>▪ 100Hz CAN output management</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.26.06</b>	Oct, 5th 2018	<ul style="list-style-type: none"><li>▪ Fixed bug on backlight set in OFF mode</li><li>▪ Fixed power off for external modules when Solo 2 DL is in charging mode</li><li>▪ Fixed bug on Digital output priority handling</li></ul> <p><b>External module</b></p> <ul style="list-style-type: none"><li>▪ <b>25.47</b> Lambda</li></ul>
<b>02.24.05</b>	Sep, 21st 2018	<ul style="list-style-type: none"><li>▪ Custom pages with pressure channels: unit of measure is selectable for each individual channel</li><li>▪ Performance race: fixed missing performance entry in data recall</li><li>▪ Fixed bug in led bar handling with predictive lap time</li></ul> <p><b>External modules</b></p> <p>No changes</p>

## Solo 2 DL Release history

Page 6

Version	Date	Change/additions
<b>02.22.81</b>	Jul, 26th 2018	<ul style="list-style-type: none"><li>▪ Fixed power consumption in low power mode (board REV00)</li><li>▪ Fixed multiplexed CAN protocols management</li></ul> <b>External modules</b> No changes
<b>02.22.67</b>	Jun, 29th 2018	<ul style="list-style-type: none"><li>▪ Added automatic start data recall at the end of the new test recorded</li><li>▪ Fixed bug in Predictive time calculation that in some cases, with high speed applications, caused bad behavior</li><li>▪ Fixed bug in System Info menu in "Hw revision" text display</li></ul> <b>External modules</b> No changes
<b>02.22.65</b>	Jun, 22nd 2018	<ul style="list-style-type: none"><li>▪ Improved suspend/powerup handling</li><li>▪ Support for board revisions C and E</li></ul> <b>External modules</b> No changes
<b>02.22.58</b>	May, 31st 2018	<ul style="list-style-type: none"><li>▪ Support of k-line protocols</li></ul> <b>External modules</b> No changes
<b>02.22.52</b>	May, 18th 2018	<ul style="list-style-type: none"><li>▪ Added "All Laps" data recall page and "Speed graph with track" data recall page</li><li>▪ Added in "Wi-Fi" menu the possibility to choose the Wi-Fi channel to use instead of a random selection at boot</li><li>▪ Fixed issue that, sometimes, after a shut down of the system, didn't allow to switch on again the Solo 2 DL</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>25.47</b> Lambda</li></ul>